
Α	REVISED: 1-9-87			
В	REVISED.	TA.	2-24-95	Plot
C	REVISED.	TA	8-17-95	12



ROLLER AND STRIKE SHOULD BE IN COMPLETE CENTER ALIGNMENT CAN BE INSTALLED ON TOP RAIL , BOTTOM RAIL OR ANY INTERMEDIATE POSITION ON THE DOOR.

FASTENER DETAILS:

SUPPLIED WITH 5 ea.
$$\frac{1}{4}$$
 -20×1 $\frac{1}{4}$ FH, UC, PH, MS

3 ea. $\frac{1}{4}$ -20 EXP. SHIELD

5 ea. $\frac{1}{4}$ +1 $\frac{1}{2}$ FH, PH, SMS

3 ea. $\frac{1}{4}$ ×1 $\frac{1}{2}$ PLASTIC BANTAM PLUG.

3 ea.
$$\frac{1}{4}$$
-20



3528 Emery Street, P.O. Box 23277 Los Angeles, CA 90023, USA

1254

STOP/HOLDER

DR. BY: L.R.

DWG. NO. 11545

Date Requested:_ Book No. This template is provided for use only on the job for which it was requested. Trinco reserves the right to make design changes without notice.